




NITRO 50



Product views	1. USB 3.2 Gen 1 port	8. USB Type-C [™] port (USB 3.2 Gen 2x2)	-
	2. USB 3.2 Gen 1 port	9. Two USB 2.0 ports	
	3. Headset / speaker jack	10. Audio jacks	
	4. Microphone jack	11. USB 3.2 Gen 2 port	
	5. Power button	12. Ethernet (RI-45) port	
	6. Qi wireless charger	13. Power connector	
	7. Two USB 3.2 Gen 2 ports		
Operating system	Windows 11 Home 64-bit		
	UEFI Shell		
	No OS		
CPU and chipset	AMD RYZEN™ 9 7900 Desktop Processor		
	AMD RYZEN™ 7 7700 Desktop Processor		
	AMD RYZEN™ 5 7600 Desktop Processor		
Memory	16 GB / 8 GB DDR5 4800 MHz UDIMM		
	 Up to 32 GB of Dual-channel DDR5 4800 MHz 		
Storage	Hard disk drive		
	 2 TB / 1 TB 3.5-inch 7200 RPM 		
	 1024 GB / 512 GB / 256 GB M.2 2280 PCI-e Gen4 SSD 		
Graphics	AMD Radeon [™] RX 7600 with 8 GB of GDDR6		
	NVIDIA® GeForce RTX [™] 4060 with 8 GB of GDDR6		
Audio	DTS:X [®] Ultra		
Communication	WLAN		
	 802.11ax/ac/a/b/g/n, Wi-Fi 6 and Bluetooth[®] 5 		
	 802.11ax/ac/a/b/g/n, Wi-Fi 6E and Bluetooth[®] 5 		
	LAN		
	 Realtek® 8118AS Dragon Gigabit Ethernet 		
Expansion slot(s)	PCIe x16 slot: 1		
	 M.2 slot (for SSD): 2 		
	M.2 slot (for WLAN): 1		
Dimensions	175 (W) x 386 (D) x 392 (H) mm (6.89 x 15.2 x 15.43 inches)		
Power supply and	Power supply		
adapter	 500 W PFC, auto-sensing, 80PLUS* Gold, ATX 		
Windows Desktop	In-House	Search	
	Acer Care Center	NitroSense	
Apps	Acer Product Registration	Productivity	
	Acer User Experience Program Framework	Microsoft Office	
	Quick Access	Microsoft Office Installer	
System	RoHS		
compliance			
	USB keyboard and mouse		
Options and	Wireless (2.4 GHz RF) keyboard and mouse		
accessories	Wireless (2.4 GHz Kr) Keyboard and modse Wireless charging (Max. output power: 10 W)		
Certification	CE, FCC, CB		
Certification	CL, I CC, CD		

As a phenomenon known to thin-film transistors (TFTs), liquid crystal displays (LCDs) commonly exhibit a small number of discoloration dots, as so-called "non-conforming pixels." This phenomenon is a limitation of TFT LCD technology, not a product defect, and as such is not covered by Acer's warranty. In a continuing effort to improve the quality of our products, information in this document is subject to change without notice. Images shown are only representations of some of the configurations available for this model. Availability may vary depending on region.

© 2023. All rights reserved.

Microsoft and Windows are registered trademarks of Microsoft Corporation.

About Acer